

▶▶▶ **TRANSFER INSTRUCTIONS**

Instructions for Printing onto **dark Paper & Carton**
with **Laser-Light (No-Cut)**

für VECTORS & PHOTOS

**1-PAPER-SYSTEM FOR
LED-PRINTERS WITH WHITE TONER**

▶ **PRINT SETTINGS**

ONLY FOR OKI PRINTERS WORKING WITH WHITE TONER

Paper & Print Setting: Transparent Foil, Multi Purpose-Tray
White Toner Darkness (Calibration in the Printer Menu): +3
Image Mode: Mirror Image, CMYK Mode (not RGB), Color Print, White On

TRANSFER SETTINGS

	AUTOMATIC HEAT PRESS	MANUAL HEAT PRESS
TRANSFER	180°C (356°F), 15 sec., 2-3 bar (medium pressure)	180°C (356°F), 30 sec., medium pressure

▶▶▶ **TRANSFER APPLICATION**

- ▶ Place your Transfer on your piece of carton or paper and press it with **180°C (356°F)** for **15 seconds** with **2-3 bar** medium pressure.
- ▶ Remove the paper after **5 - 10 sec.**